



NOTES:

PTC-IIusb FSK/PSK audio level will need to be adjusted.

Micom radios will get hot if not using factory cooling tray. Recommend setting power to medium.

Micom radios with 44 pin accessory connectors use Mobat FLN8276A 25pin/44pin adapter

C1, C2, C3 and C4 Radio Shack 272-0131

T1 & T2 XFMR6K6 1:1 600Ω

Henry D. Kenealy
PG00019185 & K1DOS

Cable for Micom Radio and Paclink Program

D R A F T (NOT TESTED)	Size	FSCM No.	DWG No.	Rev
			1	G
05/21/09	Scale			Sheet 1 of 1